



Octagon Sign Base

1. Insert the sign pole, making sure that it's in line with the base's interior nub. Using an Allen wrench, insert tamper proof screw in the designated hole at the top of the base
2. Fill the Sign Base with chosen filler and reattach the cap.
2a. We suggest using water or our water and base gel mixture for optimal performance but concrete and sand are options as well.
3. Pre-drilled holes available for signage. Specify sign size with sales rep during the ordering process

For locations that reach freezing temperatures, only fill base with 18 gallons of water or base gel mixture to allow expansion when frozen, otherwise, fill up to 22 gallons



2525 Clark St.
Detroit, MI 48209
1-866-825-8659 • www.idealshield.com